

ATTACHMENT 2

Photographs of Damaged FDR




Figure 1. EgyptAir Flight 990 flight data recorder, side view.



Figure 2. Flight data recorder with faceplate and armored enclosure removed from FDR chassis.



Figure 3. Flight data recorder armored enclosure opened with coverplate removed, exposing tape.